

541/1.

- 5

6. The assembly of claim 4, wherein said contacts are less thick and more narrow than those conforming to RJ-standards.

7. The assembly of claim 6, wherein the thickness of said contacts is about 25% to about 75% below that required under the RJ-standards, and the width of said contacts is about 5% to about 15% below that required under the RJ-standards.

8. The assembly of claim 4, wherein said receptacle is configured to receive plugs that conform to the RJ-11 standard

9. The assembly of claim 4, wherein said receptacle is configured to receive plugs that conform to the RJ-45 standard

10. The assembly of claim 9, wherein said contacts are sufficiently compliant such that if an RJ-11 plug is inserted fully into said receptacle, the elastic limit of said contacts is not exceeded.

11. The assembly of claim 1, wherein said contacts have a normal force less than about 50g.

12. The assembly of claim 1, wherein the thickness of said contacts is about 0.005" to about 0.014" and the width of said contacts is about 0.014" and about 0.016".

13. The assembly of claim 1, wherein said housing comprises one receptacle.

- said receptacle.

Gold 32 Gold 33